Thermostat display

An example home · Flagler County, FL



PHOTOGRAPHER NOTES

Set to 78, cooling, fan on auto.

Photographed Oct 14, 9:07 AM
Visit on Oct 14, 2026

Humidity reading

An example home · Flagler County, FL



Each room: ceiling and walls

An example home · Flagler County, FL



Under the kitchen sink

An example home · Flagler County, FL



Photographed Oct 14, 9:13 AM
Visit on Oct 14, 2026

Under each bathroom sink

An example home · Flagler County, FL



Photographed Oct 14, 9:15 AM
Visit on Oct 14, 2026

Floor beside each tub and shower

An example home · Flagler County, FL



Water heater base

An example home · Flagler County, FL



Photographed Oct 14, 9:19 AM
Visit on Oct 14, 2026

Air handler and its drain line

An example home · Flagler County, FL



Photographed Oct 14, 9:21 AM
Visit on Oct 14, 2026

Doors and windows, as found

An example home · Flagler County, FL



Photographed Oct 14, 9:23 AM
Visit on Oct 14, 2026

Front of the house

An example home · Flagler County, FL



Photographed Oct 14, 9:25 AM
Visit on Oct 14, 2026

Front door

An example home · Flagler County, FL



Photographed Oct 14, 9:27 AM
Visit on Oct 14, 2026

Mailbox

An example home · Flagler County, FL



Left side of the house

An example home · Flagler County, FL



Photographed Oct 14, 9:31 AM
Visit on Oct 14, 2026

Right side of the house

An example home · Flagler County, FL



AC unit

An example home · Flagler County, FL



Photographed Oct 14, 9:35 AM
Visit on Oct 14, 2026

Back of the house

An example home · Flagler County, FL



Driveway

An example home · Flagler County, FL



Photographed Oct 14, 9:39 AM
Visit on Oct 14, 2026

Outdoor water spigot

An example home · Flagler County, FL



PHOTOGRAPHER NOTES

Nothing to note.